




## 4" Repair Clamp - Corrosion





### Introduction

- Corrosion on 4" spool full length, close to one of the flange welds
- 4" pipe repair clamp 90bar
- Corrective Maintenance
- PED class
- Pressure material
- Full MRB



## 4" Repair Clamp - Corrosion



### Contact for this product is:

**Kenneth Olaf Rosén:** Senior Project Manager AOGV - IK Norway  
T: +47 992 79 828

