




4" Repair Clamp - Corrosion





Introduction

- Corrosion on 4" spool full length, close to one of the flange welds
- 4" pipe repair clamp 90bar
- Corrective Maintenance
- PED class
- Pressure material
- Full MRB



4" Repair Clamp - Corrosion



Contact for this product is:

Kenneth Olaf Rosén: Pipe Intervention & AOGV Manager - IK Norway
T: +47 992 79 828

